

No. AEE/PWP&IWTD Sub Div/Bly/PB/Fitness Cert/2019-20

Office of the Assistant Executive Engineer, P.W.P & I.W.T.D Sub div, Ballari.

To,

Chairman, Samskruthi School, Gonal, Rupanagudi Road, Ballari. 1544

08/01/2020

Sir,

Sub: Samskruthi School -Survey No: 31-B/3B, Gonal (Rupanagudi Road)
Building Fitness/ safety Certificate requested-reg.

Ref: Your letter Dated: 06.01.2020.

=====

With reference to the above cited subject, Sri. B.Vijaya Bhasker, A.E. Working in our sub-Division has inspected the Samskruthi School, building in Survey No. 31-B/3B, Gonal on 08/01/2020 and submitted the report that the structure of the school building is Fit/safe for running the classes. Accordingly I am here with certifying the structure of the above said school building is Fit/safe for running the classes.

Yours Faithfully,

Assistant Executive Engineer, PWP&IWTD, Sub Division, Ballari.